

HAWKESBURY LOCAL HERITAGE ASSISTANCE FUND 2023/2024

Examples of Minor Maintenance/Conservation Works Carried out to Heritage Listed Properties

BEFORE COMPLETION



Damaged chimneys needed repointing.

AFTER COMPLETION



Completed repointing works to chimneys helps retain the heritage value and character of this heritage listed house, and brought back the chimneys' original appearance.

BEFORE COMPLETION



To prevent further fretting of this wall and the sandstone chimney, replacement of the existing cement mortar with lime based mortar was needed.

AFTER COMPLETION



Repointed wall with lime based mortar with the correct mixture prevents further fretting. The completed works provide improved protection to the wall.

BEFORE COMPLETION



Minor maintenance was needed to replace badly deteriorated timber eaves.

AFTER COMPLETION



Completed works provides improved protection and good appearance to the timber ceiling as well.