

# HAWKESBURY LOCAL HERITAGE ASSISTANCE FUND 2022/2023

Examples of Minor Maintenance/Conservation Works Carried out to Heritage Listed Properties

## BEFORE COMPLETION



Damaged chimneys needed repointing.

## AFTER COMPLETION



Completed repointing works to chimneys helps retain the heritage value and character of this heritage listed house, and brought back the chimneys' original appearance.

## BEFORE COMPLETION



To prevent further fretting of this wall and the sandstone chimney, replacement of the existing cement mortar with lime based mortar was needed.

## AFTER COMPLETION



Repointed wall with lime based mortar with the correct mixture prevents further fretting. The completed works provide improved protection to the wall.

## BEFORE COMPLETION



Minor maintenance was needed to replace badly deteriorated timber eaves.

## AFTER COMPLETION



Completed works provides improved protection and good appearance to the timber ceiling as well.